



Region II
300 McGaw Drive - 2nd Floor, Raritan Center
Edison, NJ 08837 • (201) 225-6116

TECHNICAL ASSISTANCE TEAM FOR EMERGENCY RESPONSE REMOVAL AND PREVENTION
EPA CONTRACT 68-01-6669

TAT-02-F-03438

MEMORANDUM

TO: Charles E. Fitzsimmons
Response and Prevention Branch, U.S. EPA

FROM: William Schoellkopf, TAT II PM *jm*
James Manfreda, P.E., TAT II QC

SUBJECT: SPCC Field Inspection
Lancia Oil Company
340 South River Street
Hackensack, NJ 07601

DATE: February 17, 1987

In accordance with TDD #2-8611-42, an SPCC field inspection was conducted at this facility on November 19, 1986.

Prior to conducting the inspection, Mr. Tom Harrington of the New Jersey Department of Environmental Protection (NJDEP) Metro Region was contacted and he stated that he would be unable to attend the inspection.

The SPCC field inspection began at 0900 hours. Mr. Ugo Lancia, President, discussed the facility. A tour of the facility followed.

The oil storage facilities at this site consist of the following:

- 1) Total 1,200,000 gallons of #2 oil stored in two (2) aboveground, diked tanks.
- 2) Total 15,000 gallons of kerosene stored in an aboveground, diked tank.

235241



Roy F. Weston, Inc.

SPILL PREVENTION & EMERGENCY RESPONSE DIVISION

In Association with ICF Inc., Jacobs Engineering Group Inc., C.C. Johnson & Associates, Inc., and Tetra Tech, Inc.,

OBSERVATIONS:

The facility appears to be fully in compliance. Secondary containment appears to be adequate. Drainage from the loading rack pools on an asphalt and concrete surface just south of the control room. During this inspection stormwater runoff was indeed pooled in this area. Absorbent is stored in a shed directly adjacent to the loading rack.

The SPCC plan was not available at this office (it was at another office). However, a phone call verified that the EPA Region II Office in Edison, New Jersey has a copy of the facility's revised 1984 plan. A desk review at that time found the plan to be in compliance, but no field inspection was conducted for verification.

Mr. Lancia should note that the tri-annual plan review by management is due in 1987, and that a copy of the SPCC plan must be available at the facility.

Attachments

WS/JM:ls

U.S. ENVIRONMENTAL PROTECTION AGENCY REGION 2
SPCC FIELD INSPECTION FORM

NAME OF FACILITY- Lancia Oil TELEPHONE NUMBER- (201) 342-5454
FACILITY CONTACT/TITLE- UGO Lancia PLAN CERTIFICATION-
President SEE A. BELOW
FACILITY ADDRESS- 340 South River St. PLAN STATUS (C or N)
Hackensack NJ 07601

CAPACITY-(TYPE OF OIL/ABOVE OR BELOW)
400,000 GAL #2 oil ABOVE
800,000 GAL #2 oil ABOVE
15,000 GAL KEROSENE ABOVE (USUALLY STORE 3,000 - 4,000 GAL)

COMMENTS/NONCOMPLIANCE ITEMS-

A. SPCC PLAN: NOT AVAILABLE AT OFFICE.

EPA Region II has copy of 1984 revised plan. A desk review at that time found the plan to be in compliance, but no field inspection was conducted to verify.

B. FIELD INSPECTION:

Facility appears to be in compliance. Dike appears adequate for containment of 3 tanks. Drainage from loading rack pools on asphalt/concrete surface just south of control room. Absorbent is stored nearby.

SCHEDULE FOR IMPLEMENTATION OF THE ABOVE ITEMS IS DUE: NOT APPLICABLE


INSPECTOR SIGNATURE/DATE/PHONE #: William Schoellkopf William Schoellkopf 11/19/86

FACILITY CONTACT/DATE: [Signature]

CORRESPONDENCE TO: CHIEF, INCIDENT RESPONSE AND
PREVENTION SECTION
U.S.E.P.A. REG.2, BLDG. 209
WOODBIDGE AVE.
EDISON, N.J. 08837

201-321-6608

6. FIELD DRAWINGS (Attach more sheets if needed, and show north arrow or other orientation)



NOT TO SCALE

FACILITY

LANCIA OIL

INSPECTION DATE

INSPECTOR

WILLIAM SCHOELLKOPF

7. PHOTOGRAPHS (Attach more sheets if needed)

SUBJECT LANCIA OIL CO	FACILITY
PHOTOGRAPHER	WITNESSES
WITNESSES	WITNESSES
DATE/TIME/DIRECTION	CAMERA/FILM/ATTACHMENTS
SUBJECT	FACILITY
PHOTOGRAPHER	WITNESSES
WITNESSES	WITNESSES
DATE/TIME/DIRECTION	CAMERA/FILM/ATTACHMENTS

ATTACH PHOTOGRAPHS HERE



FRONT VIEW OF FACILITY



SIDE VIEW OF STORAGE TANKS